

The Department of Energy's Office of River Protection tank farm contractor, Washington River Protection Solutions, has determined that 19 of the 20 single-shell tanks showing decreased liquid levels at the Hanford Site are not actively leaking. The one tank previously identified as leaking, T-111, appears to be stabilizing.

The cleanup of tank waste at Hanford's nuclear facilities and protection of workers, the public and the environment remains a high priority for the Department. We will continue to keep the State of Washington, Congress and other key stakeholders apprised of the situation as we continue to monitor the liquid levels inside the single shell tanks.